



中 一

检测单位 (盖
Detection unit (seal)

编 制 人 周 蕊 蕊

Compiled by

周 蕊 蕊

Inspected by

周 蕊 蕊

5

The image shows a table with multiple rows and columns. The content is almost entirely obscured by heavy black redaction bars. Only a few faint lines and small fragments of text are visible, particularly in the middle and lower sections of the table. The table appears to have several columns, but their headers and the data within them are illegible.

2023

噪声监测点



监测点名称	监测时间	昼间噪声	夜间噪声
1# 厂界西侧	14:01	62	52
2# 厂界南侧	14:08	61	50
3# 厂界东侧	14:14	59	51
4# 厂界北侧	14:21	58	50

工业企业厂界环境

GB 12349-2008

噪声监测点



监测点名称	监测时间	昼间噪声	夜间噪声
1# 厂界西侧	14:01	62	52
2# 厂界南侧	14:08	61	50
3# 厂界东侧	14:14	59	51
4# 厂界北侧	14:21	58	50



共
同
公
司
印